

U. S. Department of Agriculture

FOREST SERVICE

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 27 W. 5th Mer.

SW 1/4 Corner common to Sections 20, 21, 29, and 38

Corner consists of a Post (set) in place

State condition good

Dimensions above ground 3.2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

3	2	1	2
20	29	21	2

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

3/27/35 _____ (Signature)

(Date) _____ (Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side

inches diameter, on the

Metal Location Poster is on a *FENCE POST*



(Make sketch of topography near Corner)

T. 148 N. R. 37 W. *sec 37*

U. S. Department of Agriculture
FOREST SERVICE

R1B

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.

Section Corner common to Sections
20, 21, 29, and 28

Corner consists of a post (not) in place

State condition good

Dimensions above ground 32 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S	S	S	S
20	29	28	21
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None			

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner placed too recently.

Ray Nelson
(Signature)

3/27/35
(Date)

Chief of Party
(Title)

