

U. S. Department of Agriculture

FOREST SERVICE

E1-2

Posted

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 27 S. Mer.

Meander Corner common to Sections 1, 6, and

Corner consists of a Meander Post (not) in place State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

	7	6	
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Mc	Mc		

Species ASPEN ASPEN

Diameter 12 9

Bearing N 07 E 6' S 07 E 5'

Distance 70 ft. 25 ft.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John Karaga Gilley (Signature)

7-18-34 (Date)

(Title)

Trail leading from  
marker to  
Also a snow stake  
Set away from marker  
about 2 feet

Corner again.  
Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *west*

side of *pole*

tree *7* inches diameter, on the *North*

Metal Location Poster is on a *telephone pole*



(Make sketch of topography near Corner)