

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

*Copied  
 Posted  
 5/34  
 V14*

----- NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. 148 R. 27 5 Mer.

----- Corner common to Sections  
27, 34, -----, and -----

Corner consists of a stone ----- (not) in place  
 State condition -----

Dimensions above ground ----- inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

-----  
 -----  
 -----

-----  
 (Signature)

-----  
 (Date)

-----  
 (Title)

16" poplar stub N E scribbled 1/2 S B T

14" poplar stub S E scribbled 1/2 S B T

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.