

U. S. Department of Agriculture

FOREST SERVICE

P-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 97 W Mer.

Corner common to Sections 22, and 23

Corner consists of a Post (not) in place

State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Face of	INCHES DIAMETER	NW	SW	SE	NE
Side of		<u>1/4</u>	<u>1/4</u>	<u>1/4</u>	<u>1/4</u>
Post		<u>S</u>	<u>S</u>	<u>S</u>	<u>S</u>
Location		<u>22</u>	<u>22</u>	<u>22</u>	<u>22</u>

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S</u> <u>22</u>			
<u>BT</u>			

Species T22a

Diameter 12 1/2

Bearing S. 80° E

Distance 04

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Signature) \_\_\_\_\_  
A. Deol. COLREL

(Date)

(Title)

W 62a

Corner again.

Give any further facts which will aid in finding this

chains distant.

104

From which this Corner bears

West

side of


Post

tree inches diameter, on the

West

Metal Location Poster is on a

Corner post



(Make sketch of topography near Corner)

P-15

T. 148 N. R. 27 W. S. 2 Mer.