

U. S. Department of Agriculture
FOREST SERVICE

N-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.

1/4 Corner common to Sections
15, and 22

Corner consists of a wooden post (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>8</u>		<u>5</u>	
<u>15</u>		<u>22</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>			
<u>5</u>			
<u>15</u>			
<u>BT</u>			

Species Tax

Diameter 7"

Bearing N. 24° W.

Distance 30

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


(Signature)

(Date)

(Title)

62

Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

Mer.

5

R. 27W

T. 148N

N-15