

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

J-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W S. 76 Mer.

Corner common to Sections

10, and 15

Corner consists of a Tree post (not) in place

State condition Fair

Dimensions above ground 4" x 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
5		5	
10		15	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>11000 ft</u>			

Species T22

Diameter 12"

Bearing S. 4° E

Distance 13

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Signature)

(Date)

(Title)

45

Corner again.

Give any further facts which will aid in finding this

chains distant.

109

from which this Corner bears

N 110° W


side of

tree 8 inches diameter, on the

N 87° E

Metal Location Poster is on a

Cedar



(Make sketch of topography near Corner)

R

Mer.

U-13  
T