

U. S. Department of Agriculture
FOREST SERVICE

P-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *27* Mer. *5th*

1/4 Corner common to Sections
22, and *23*

Corner consists of a _____ (not) in place
State condition *placed by*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>FT</i>			

Species *Iron* _____

Diameter *5"* _____

Bearing *127°* _____

Distance *376* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

_____ (Signature)

_____ (Date)

_____ (Title)

[Faint, illegible handwriting]

*Another Metal/Poster
a fence post 0.19 5.5
North of corner*

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears
SM 2.10

side of

~~tree~~ inches diameter, on the

Metal Location Poster is on a *regular post*



(Make sketch of topography near Corner)

P-17

Mer.

R

T