

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 128 S R. 27 W 5th Mer.


14 Corner common to Sections
 _____, _____, 14, and 23

Corner consists of a _____ (not) in place
 State condition Placed by crew

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Stump Stump

Diameter _____

Bearing S 60° E N 30° W

Distance 1.15 1.27

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

 (Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

Map of



(Make sketch of topography near Corner)

Mer.

T. 118 N. R. 27 W.

5 24