

U. S. Department of Agriculture

FOREST SERVICE

T-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th - Mer.

14 - Corner common to Sections

25, and 26

Corner consists of a J-Pine Post (not) in place


State condition New

Dimensions above ground 4x4x-36" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species (JPine) JP. Foliata -

Diameter 12" 12

Bearing S-81°W N 84°E

Distance 37 4125-

Do you believe this to be a genuine Land Office Corner

If not, why?


Balke (Signature) Leader (Title)

4/23/37

(Date)

Corner is located on N.E. corner of spring stand - D. Land on three sides of corner has been haggled off.

Corner again.
 Give any further facts which will aid in finding this chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148N R. 27W 5th Mer.