

U. S. Department of Agriculture

FOREST SERVICE

R23  
P.

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148<sup>th</sup> R. 27<sup>th</sup> 5th Mer.

Quarter

Corner common to Sections

24, and 25

Corner consists of a Wood Post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S 24		S 25	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 24			
B. T.			

Species Aspen

Diameter 12"

Bearing N 290° E

Distance 54 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Don R. ...*  
(Signature)

D. Rigar Chief of party  
(Title)

6/7/35  
(Date)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Corner again.

Give any further facts which will aid in finding this  
 chains distant,  
 from which this Corner bears  
 side of  
 tree \_\_\_ inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

R-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. R7W 5th Mer.

1/4 Corner common to Sections

24, and 25

Corner consists of a Oak (not) in place


State condition new

Dimensions above ground 4'4" x 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Aspen

Diameter 8" 15"

Bearing S-22°30'W N-28°E

Distance .63 .54

Do you believe this to be a genuine Land Office Corner? No

If not, why? Re-established by  
Burns & Allen, Surveyors

Bull  
(Signature)

4/29/37  
(Date)

(Title)

Land cuts over to East  
to west - No. type -  
Highland - Also level -

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148 N R. 23 W Mer.