

U. S. Department of Agriculture

FOREST SERVICE

R25  
A.

Chimneywa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148<sup>th</sup> R. 27<sup>th</sup> 5th Mer.

Section Corner common to Sections

24, 19, 25, and 30

Corner consists of a Wood Post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N. W. S. E.

24	25	30	19
----	----	----	----

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S/30	S/19		
------	------	--	--

B. T.	B. T.		
-------	-------	--	--

Species Ced. Cedar

Diameter 4" 5"

Bearing N 49° E S 55° W

Distance .73 .68

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Don R. ...*  
(Signature)

Chief of Party.

6/7/35

(Date)

(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

Section 19

tree 6 inches diameter, on the

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

R-25

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 43N R. 27W 5th Mer.

Section Corner common to Sections 24, 25, 19, and 30

Corner consists of a Cedar tree (not) in place State condition None

Dimensions above ground Under surface of Tree Trunk Sketch grooves, letters, figures, or notches, on proper face or edge. CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Table with 4 columns for tree markings. Row 1: 5-19, 5-30, witness, witness. Row 2: BT, BT, Post, Post.

Species Cedar Cedar Cedar Cedar

Diameter 5" 8" 3" 3"

Bearing N47°E S23°05'N 47°W S23°30'W

Distance 29 25 53 82

Do you believe this to be a genuine Land Office Corner? No If not, why? Established perhaps by County Surveyor. No sign of tree.

Signature: Balke

(Signature)


Title: Lumber

(Title)

(Date)

Corner again.  
 Corners corner post or stub  
 under surface of road -  
 also white-washed near  
 post - with yellow flag -  
 Marking for -

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 118N R. 27W 5th Mer.