

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.
Quarter

Corner common to Sections

28, and 19

Corner consists of a Iron pipe (not) in place



State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Bass W. Bass W. Stumps

Diameter 8" 6"

Bearing N3E S5E

Distance .18 .32

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

Walter Haberle

(Signature)

12/10/39

(Date)

Leader

(Title)

Corner again.

Give any further facts which will aid in finding this


481K chains distant.

from which this Corner bears 889E

side of Corner

tree 4 inches diameter, on the East

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 148N R. 27W 5th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

875

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 27W 5th Mer.
Quarter

Corner common to Sections
24, and 19
Corner consists of a Iron pipe (8") in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Bass W. Bass W. Stumps

Diameter 8 8

Bearing N3E S5E

Distance .18 .32

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

Walter Haberle

(Signature)

Leader


12/10/39

(Date)

(Title)

Metal Location Poster is on a Birch tree 4 inches diameter, on the East side of 48LKB chains distant. from which this Corner bears 989E

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

P-25

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.
Quarter Corner common to Sections

24, and 19

Corner consists of a Iron pine () in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S19	S19		
-----	-----	--	--

BT	BT		
----	----	--	--

Species Bass W. Bass W. Stumps

Diameter 8" 6"

Bearing N3E S5E

Distance .18 .32

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

Walter Haberle

(Signature)

12/10/39

Leader

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

481K8 chains distant.

from which this Corner bears


889E

side of

CORNER

tree 4 inches diameter, on the East

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T 148N R 27W 5th Mer.