

U. S. Department of Agriculture  
FOREST SERVICE

525

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 26427 W. 5th Mer.

Section Corner common to Sections  
12, 7, 13, and 18

Corner consists of a Post (not) in place

State condition good

Dimensions above ground 16 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S-12	S-13	S-18	S-7
------	------	------	-----

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Illegible			

Species Elm

Diameter 30"

Bearing N. 32° W

Distance 32 links

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

*Harmon Adams*

(Signature)

1/10/35


(Date)

Asst. Leader, CCC

(Title)

Corner again.  
 A road has been started and is out  
 out to road 1/4 mile south. Corner is  
 in center and end of road.

Give any further facts which will aid in finding this  
 chains distant. 0.32  
 from which this Corner bears S 32° E  
 side of Post  
 tree 30 inches diameter, on the NW  
 Metal Location Poster is on a Elm



(Make sketch of topography near Corner)