

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST E-25

CORNERS OF THE PUBLIC SURVEY

T. 48 N. R. 27 W. Mer.

Corner common to Sections

1, 6, 12, and 7

Corner consists of a *aspens* ~~tree~~ in place

State condition *poor*

Dimensions above ground *80* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

to edge of	to edge of	to edge of	to edge of
N	W	E	S

S	S	S	
1	12	7	6
NW	SW	SE	NE

Mound of *is located*

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

MC S 12	MC S 6		
B.T.	B.T.		

Species *bas oak*

Diameter *10" 12"*

Bearing *S 42° W N*

Distance *21 LINKS 12 LINKS*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? *yes*

W. J. ...

(Signature) *W. J. ...*
(Title) *... Leader*

(Date) *6/25/35*

Faint, illegible text on ruled lines at the top of the page.

Corner again.

Give any further facts which will aid in finding this

13. Link chains distant.

from which this Corner bears

South

side of

oak

tree 12 inches diameter, on the

S.E.

Metal Location Poster is on a

oak



(Make sketch of topography near Corner)

T. 143N R. 27W 5TH Mer.