

Form 274-0--Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST C-25

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 27 W Mer.

4 Corner common to Sections
 _____, _____, and 6

Corner consists of a Placat (not) in place



State condition by crown

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>45</u>			
<u>BT</u>			

Species Tam

Diameter 8"

Bearing N 75° E

Distance 405 Ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Emmett
 (Signature)

6/25/35
 (Date)

Chief of Party
 (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

21

from which this Corner bears

S 10 W


side of

S 6

tree 5 inches diameter, on the

Spr

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 R. 574 Mer.