

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

2-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section Corner common to Sections  
4, 5, 22, and 33

Corner consists of a Order post (not) in place  
 State condition Fair

Dimensions above ground 3" x 30" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

S	S	S	S
32	5	4	33
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No original B.T. Found

Halerh  
 (Signature)

4/8/38  
 (Date)

Leader  
 (Title)

6.7. Spruce 8" 5.1 E  
26 LINES

Corner again.

Give any further facts which will aid in finding this


34 LINES chains distant.

From which this Corner bears N 8° W

side of trees

tree 10 inches diameter, on the south

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

A-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section Corner common to Sections 4, 5, 32, and 33

Corner consists of a Cedar post (not) in place State condition Fair

Dimensions above ground 3" x 20" inches Sketch grooves, letters, figures, or notches, on proper face or edge.

N	W	S	E

5	5	5	5
32	5	4	33
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No. ORIGINAL B.T.'s FOUND

Haberle (Signature)

1/8/32 (Date)

Leader (Title)

Corner again. *with space 8' 5 1/2" all links*

Give any further facts which will aid in finding this


*SHILLY* chains distant.

From which this Corner bears *N 80 W*

side of *Tree*

tree *10* inches diameter, on the *South*

Metal Location Poster is on a *Space*



(Make sketch of topography near Corner)

T. 148 R. 28 Mer. 6-14

U. S. Department of Agriculture

FOREST SERVICE

~~4~~-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section Corner common to Sections 4, 5, 32, and 33

Corner consists of a Cedar post (not) in place State condition Fair

Dimensions above ground 3" x 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

5	5	5	5
32	5	4	33

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? NO ORIGINAL B.T.S FOUND

Haberla

(Signature)


Leader

(Title)

1/8/38 (Date)

Corner again.  
W. Spruce 8" S. 10 E  
36 LINKS

Give any further facts which will aid in finding this  
34 LINKS chain distant.  
From which this Corner bears  
N 80 W  
side of tree  
tree 10 inches diameter, on the South  
Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)