

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

v 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5th Mer.

Section N Corner common to Sections
28, 29, 32, and 33

Corner consists of a Tamper (not) in place

State condition poor

Dimensions above ground 2" x 2" x 15" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

5	5	5	5
29	32	33	28

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>148 N</u> <u>28 W</u> <u>528</u>	<u>148 N</u> <u>28 W</u> <u>532</u>		

Species fern tamstob

Diameter 3" 4"

Bearing N 25° E S 88° W

Distance .36 1.98

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Hakala

(Signature)

8/22/38

(Date)

Leader

(Title)


Corner again. *from 4 525° E 42 LKS W.T.*

Give any further facts which will aid in finding this *25 LKS chains distant.*

from which this Corner bears *N90° E*

side of *tree* tree *4* inches diameter, on the *west*

Metal Location Poster is on a *from*



(Make sketch of topography near Corner)

T 148 N R. 29 W 5th Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section Corner common to Sections
28, 29, 32, and 33

Corner consists of a tripart (not) in place

State condition poor

Dimensions above ground 2" x 2" x 15" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION


N	W	S	E

S	S	S	S
29	32	33	28
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T148N</u>	<u>T148N</u>		
<u>R28W</u>	<u>R28W</u>		
<u>S28</u>	<u>S32</u>		
			

Species Fam Famshb

Diameter 3" 4"

Bearing N 25° E S 85° W

Distance 3.6 1.98

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Walter H. Hale

(Signature)

Leader

(Title)

8/22/38
 (Date)

Corner again. from 4" S 85° E 42.6 Ks. WT


Give any further facts which will aid in finding this

chains distant.

25 LKS from which this Corner bears N 90° E

side of tree 4 inches diameter, on the west

Metal Location Poster is on a farm



(Make sketch of topography near Corner)

T 148N R 28W 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST V-9

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section Corner common to Sections 28, 29, 32, and 33

Corner consists of a Tam. post (not) in place

State condition post

Dimensions above ground 2" x 2" x 15 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
29	32	33	28
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 148N R 28W S. 28	T 148N R 28W S. 32		

Species Tam. 7.0st.6

Diameter 3" 4

Bearing N 25° E 589° W

Distance 36 678

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Walter Haberle

(Signature)

Leader

(Title)

8/23/38

(Date)

Corner again.
T2m N. 52.5° E 42.15 w. ft.

Give any further facts which will aid in finding this

25 LKS chains distant.

from which this Corner bears

N 90° E

side of


Tree

tree 4 inches diameter, on the

WEST

Metal Location Poster is on a

T2m.



(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 5th Mer.