

U. S. Department of Agriculture

FOREST SERVICE

Ca

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 198N R. 28W 5th Mer.

Corner common to Sections

5, and 4

Corner consists of a crossed stake post in place



State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter STUMP

Bearing 57° W

Distance 10

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

(Signature)

7/9/36

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. L. HEN R. 28 W 6 N Mer.

U. S. Department of Agriculture

FOREST SERVICE

C 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 28 W 5th Mer.

Corner common to Sections

5, and 4 (not) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		1/4
	5		5
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 5 4			
BT			

Species Birch

Diameter STAMP

Bearing 57 2/3 W

Distance 10

Do you believe this to be a genuine Land Office Corner? yes

If not, why?


(Signature)

1/9/35 (Date)

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. LASH R. 28 (D) 5<sup>th</sup> Mer.

U. S. Department of Agriculture

FOREST SERVICE

C-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 118 N R. 28 W 5<sup>th</sup> Mer.

Corner common to Sections

5 & 4

and Popular Post

Corner consists of a 1/4 Stake & (not) in place

State condition Good Condition

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	Y S		Y S
--	--------	--	--------

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Y S			
D			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Arthur H. Jager

(Signature)

Chief of Party

(Title)

7/9/35 (Date)

COORDINATE OF THE CORNER POINTS  
ELEVATION OF THE CORNER POINTS

Corner again. Give any further facts which will aid in finding this


35.7 m<sup>2</sup> remains distant.

from which this Corner bears N 11 5/8 E

side of tree

tree 4 inches diameter, on the

Metal Location Poster is on a tree



(Make sketch of topography near Corner)