

U. S. Department of Agriculture

FOREST SERVICE

*Pat'd R 17*

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1427 R. 207 5th Mer.

Section 22, 25, 27, and 26  
 Corner common to Sections

Corner consists of a small stump (not) in place

State condition Good.

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
22	27	26	23

N. W. S. E.

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 25	S 26	S 27	
B.T.	B.T.	B.T.	

Species open Pinus open

Diameter 3 1/2" 1 3/4" 3 1/2"

Bearing 66° 25° 59°

Distance .80 .82 1.27

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Harrison Adams*

(Signature)

7/11/35


(Date)

Party Chief, 000

(Title)

R-17

Metal Location Poster is on a  
 tree  $1\frac{1}{4}$  inches diameter, on the  
 side of  
 from which this Corner bears  
 1.27  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)