

517

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 Mer. 5

Corner common to Sections 10, 11, 14, and 15

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>B</i> <i>15</i>

--

<i>1</i>

--

<i>BT</i>

--

<i>BT</i>

--

Species *A. bals.* *Aspen*

Diameter *14* *15*

Bearing *S 23 W* *S 12 E*

Distance *164* *118*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

John W. Johnson

(Signature)

(Date)

(Title)

J-17

Iron Corner
Road Hotel

Road
East
West
North
South

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

5250

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)