

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

29
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 28 W 5 Mer.



1/4 Sec Corner common to Sections
2, and 35

Corner consists of a cedar sapling (not) in place
State condition A line

Dimensions above ground 24.5 in. inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of L is located L

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? ES


If not, why? No. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.
no spec. describe

Signature.

11/2/20 Date. Forest Ranger Title. 8-3027

T. 148 N. R. 28 W. 5 Mer.

(Make sketch of topography near Corner.)



Metal Location Poster is on a Cedar tree 17 inches diameter, on the South side of $\frac{1}{4}$ corner from which this Corner bears S 180 W 11 chains distant. Give any further facts which will aid in finding this Corner again. E & W Line 112 ft and 60 ft ways. stream chains to East.