

U. S. Department of Agriculture

FOREST SERVICE

*Posted E21*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 28 W 5 Mer.

Section Corner common to Sections

1, 2, 11, and 12

Corner consists of a POST (not) ~~in place~~



State condition Good - Painted

Dimensions above ground 4 1/2" high, 6" dia inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Could find no bearing trees, on account of clearing. Corner is in center of road.

Milton J. Johnson  
(Signature)


(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

15 links chains distant. (approximate)  
from which this corner bears South 7° W  
side of County Road B  
6" inches diameter, on the N. side  
Metal Location Poster is on a Painted Post



(Make sketch of topography near corner)

T. 148 N. R. 28 W. Mer. 5