

U. S. Department of Agriculture  
FOREST SERVICE

V 23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 5th Mer.

1/4

Corner common to Sections

25, and 36

Corner consists of a *Aspen* (not) in place

State condition *good*

Dimensions above ground *4x4x16"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*+178m  
R290  
5026*

*B.T.*


Species *OAK*

Diameter *14"*

Bearing *S3°15'E*

Distance *8.5*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *No original B.T. found*

*Walter Habick*

(Signature)

*9/22/38*

(Date)


*Leader*

(Title)

Corner again. *It is about a 1/2 mile from*

Give any further facts which will aid in finding this *18 LKS chains distant.*

from which this Corner bears *54.30' E* side of *Tree* tree *3* inches diameter, on the *North* Metal Location Poster is on a *oak*



(Make sketch of topography near Corner)

T 148 R 28 S 4 Mer.

Form 874-9—Revised May, 1918  
 U. S. DEPARTMENT OF AGRICULTURE  
 FOREST SERVICE

V23  
 [Handwritten initials]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 178 N R. 28 W 5 Mer.



1/4 Corner common to Sections  
25, and 36

Corner consists of a 20" N. Pine (not) in place  
 State condition and thrown - 1 log removed

Dimensions above ground \_\_\_\_\_ inches.  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 Cr  
3.25

B.T.

Species W. Oak  
 Diameter 12"  
 Bearing S 11° E  
 Distance 65 Lks.

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

Wm H. Fletcher  
 Signature.


Forest Ranger  
 Title.

12/6/28  
 Date.

T. 148 N. R. 28 W. 5th Mer.

8-3027

(Make sketch of topography near corner.)



Metal Location Poster is on a *White Oak*

tree *12* inches diameter, on the *N*

side of *Tree*

from which this Corner bears *511° W*

*65* links ~~chains~~ distant.

Give any further facts which will aid in finding this

Corner again.

Marker is on *B.T.*

Approx. *90* links *S* of inside

*V* in Indian name road, on

*S* edge of *Out over pine*

*Knoll.*

U. S. Department of Agriculture  
FOREST SERVICE

V-23

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 145N R. 28W 5th Mer.

1/4 Section Corner common to Sections  
25, and 36Corner consists of a Aspen post (not) in placeState condition goodDimensions above ground 4" x 4" x 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

71814 R28W 5th 36			
BT.			

Species OakDiameter 14"Bearing 53° 15' EDistance .85'Do you believe this to be a genuine Land Office Corner? NoIf not, why? No original P.T.foundWalter Habeck

(Signature)

Leader

(Title)

9/22/38

(Date)

*D. F. ...*

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *54°30'E*

side of *Tree*

tree *3* inches diameter, on the *North*

Metal Location Poster is on a *0214*



(Make sketch of topography near Corner)

T. L. H. R. 2862 gfk Mer.

U. S. Department of Agriculture

FOREST SERVICE

V-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 192N R. 28W 5th Mer.

1/4 sections Corner common to Sections 25, and 36

Corner consists of a Aspen (set) in place

State condition good

Dimensions above ground 4" x 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Diagram showing cardinal positions: N, W, S, E.

Diagram showing diagonal positions: NW, SW, SE, NE.

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

7148N  
R28W  
Sec 36

BT.

Empty box for sketching bearing tree markings.

Empty box for sketching bearing tree markings.

Empty box for sketching bearing tree markings.

Empty box for sketching bearing tree markings.

Empty box for sketching bearing tree markings.

Empty box for sketching bearing tree markings.

Species A.S.M.

Diameter 19"

Bearing S 81° 15' E

Distance 85'

Do you believe this to be a genuine Land Office Corner? No

If not, why? No original B.T. found

Walter H. Fisher

(Signature)

9/22/38 (Date)

Forester (Title)

*RT. in also a willow tree*

Corner again.

Give any further facts which will aid in finding this


chains distant.

157RS from which this Corner bears S 40 30' E

side of *Tree*

tree 3 inches diameter, on the North

Metal Location Poster is on a oak



(Make sketch of topography near Corner)

Mer.

T. 148 N. R. 28 W. 5th