

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th P. Mer.
Section Corner common to Sections

4, 5, 8, and 9

Corner consists of a Corner in Center (not) in place
of Road.

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County	B. Ts.		
S 8	S 9		
B. T.	B. T.		

Species J. Pine J. Pine

Diameter 6" 6"

Bearing S. 40° W. S. 51° E.

Distance 93 61

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. Hoard

(Signature)

11/16/39

(Date)

Compass Man

(Title)

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of **Post** *Post is corner*

tree 6 inches diameter, on the **South**

Metal Location Poster is on a **Sec. Line Post**



(Make sketch of topography near Corner)

T. 148 N., R. 29 W., 5th P., Mer.