

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 29 S. 5 Mer.

1/4 Corner common to Sections _____, _____, _____, and _____



Corner consists of a Wood hub in center road (not) in place
State condition Good

Dimensions above ground 4' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ELM

Diameter 18

Bearing NW

Distance 1.5 H

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

~~sec. 6~~ inches diameter, on the

Metal Location Poster is on a

white post



(Make sketch of topography near Corner)

T. 148 R. 29 Mer.