

J-1

Form 874-9—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

part 1

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 7148N R. 30W Mer. 56

Section Corner common to Sections

7, 16, 23, and 32

Corner consists of a Wooden Stake (not) in place

State condition Good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

7148	7148	7148	7148
30W	30W	30W	30W
512	513	517	518

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

John E. Hayes
(Signature)

2/20/38
(Date)


TRAVERSE
(Title)

J-1

In location from
 Sec. 1, T. 34 N., R. 30 W.
 of the Oklahoma
 .95 sq. miles
 more north
 a better

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 34 N. R. 30-31 W. 5th Mer. U-1