

B-5

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th Mer.

N 1/6 7 - 1/16 Corner common to Sections

....., ....., 6, and 5.....

Corner consists of a Ash Post (~~not~~) in place

State condition Good

Dimensions above ground 28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar Ash .....

Diameter 14" 12" .....

Bearing S SE .....

Distance 20 Links 20 Links .....

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? .....

*G. D. Bauch*

G. D. Bauch

(Signature)

Junior Forester

(Title)

12/13/35

(Date)

B-5

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)