

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 30 5th Mer.

C 14 Corner common to Sections
....., and 5



Corner consists of a Wooden Stake (not) in place
State condition Good

Dimensions above ground 2" x 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Stump
Diameter 14"
Bearing S 40 E
Distance .79 ch

Do you believe this to be a genuine Land Office Corner? Yes
If not, why?

Henderson
(Signature)

10/24/34
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 ----- from which this Corner bears
 ----- side of
 ----- tree ----- inches diameter, on the
 ----- Metal Location Poster is on a

	Sec.		Sec.
	Sec.	Sec.	

(Make sketch of topography near Corner)

T. 148 R. 30 S. 4
 Mer. C-7

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. _____ R. _____ Mer.

_____ Corner common to Sections
5, _____, _____, and _____

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)

(Date)

(Title)


C-7

Corner to corner 188 188 188 188
 about 1 LINKS from gate.

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *30* S. *5th* Mer.

C 14 Corner common to Sections

....., and *5*
Corner consists of a *Wood stake* (not) in place

State condition *Good*

Dimensions above ground *2" x 10* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>BT</i>			

Species *S. EXMPL*

Diameter *1.4"*

Bearing *S 40 E*

Distance *279ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Harrison
(Signature)

10/24/34
(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec. 05</p>

(Make sketch of topography near Corner)

T. 114 R. 30 S. 4 Mer.