

U. S. Department of Agriculture
FOREST SERVICE

1 of 3

Crippen NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *648* R. *30* Mer. *5th*

Section Corner common to Sections
4, 5, 8, and 9

Corner consists of a *iron pipe* (not) in place
State condition *F 2.17*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 118 R-30 S-5	T 118 R-30 S-4		
----------------------	----------------------	--	--

BT	BT		
----	----	--	--

Species *Stump* *Stump*
Diameter *14"* *14"*
Bearing *S 86 W* *N 21 E*
Distance *43 ch* *30 ch*


Do you believe this to be a genuine Land Office Corner? *Yes*
If not, why? _____

A. Anderson
(Signature)

10/26/34
(Date)

Metal Location Poster is on a three inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 14 R. 30
 1-53
 E-9
 Mer.

U. S. Department of Agriculture

FOREST SERVICE

2 of 3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 30 5W Mer. Sec. Corner common to Sections


4, 5, 8, and 9

Corner consists of an Iron Pipe (not) in place State condition Good

Dimensions above ground 5 inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species L. Pine Diameter 5" Bearing N45W Distance 5 ft.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

G. D. Bauch

(Signature)

11/15/35

(Date)


S.F.

(Title)

The corner is on a ridge 5 ch. ± 50. of low ground and just west of the road.

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 14B R. 30 243 5W 6-8 Mer.

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-9

3 of 3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th P. Mer.

Section Corner common to Sections
4, 5, 8, and 9

Corner consists of a 3/4" Iron Pipe and Scribed Post (not) in place
State condition Good

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.S.			
Stumps			
BT	BT		

Species J. Pine stp J. Pine stp
 Diameter 14" 14"
 Bearing N. 87° W. N. 20° E.
 Distance 44 36

Do you believe this to be a genuine Land Office Corner? *yes.*
If not, why? _____

K. V. Styler
(Signature)

5/11/38
(Date)

Leader
(Title)

E-9


$$\begin{array}{r} 66 \\ 14 \\ \hline 80 \end{array}$$

$$\begin{array}{r} 66 \\ 14 \\ \hline 80 \end{array}$$

$$\begin{array}{r} 66 \\ 14 \\ \hline 80 \end{array}$$

$$\begin{array}{r} 66 \\ 14 \\ \hline 80 \end{array}$$

Metal Location Poster is on a *1.1 P.M.*
 tree 4" inches diameter, on the *SE*
 side of *Tree*
 from which this Corner bears *S. 33° E.*
 0.04 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 198N. R. 30W. 3+3 E-9 Mer. 5th P.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 148 N. R. 30 W. 5th P. Mer.
Section Corner common to Sections

4, 5, 8, and 9
Corner consists of a 3/4" Iron Pipe and scribed post (not) in place
State condition Good

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.s		
Stumps		

B.T.	B.T.		
------	------	--	--

Species J. Pine Stump J. Pine Stump

Diameter 14" 14"

Bearing N. 87° W. N. 20° E.

Distance 44 36

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

K. V. Styler
(Signature)

Leader


(Title)

5/11/38

(Date)

(Make sketch of topography near Corner)

T. 148 N., R. 30 W., 5th P. Mer.



J. Pine

Metal Location Poster is on a

tree 4" inches diameter, on the

S. E.

side of Tree

from which this Corner bears

S. 33° E.

0.04

chains distant.

Give any further facts which will aid in finding this

Corner again.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

*Already
Posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th Mer.

Section _____ Corner common to Sections
4, 5, 8, and 9

Corner consists of ~~an~~ iron pipe (not) in place


State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Jack Pine

Diameter 5"

Bearing N. 45° W.

Distance 5 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. D. Bauch

G. D. Bauch

(Signature)

11/15/35

(Date)


Junior Forester

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

The corner is on a ridge 5 ch. South of low ground and just west of the road.



(Make sketch of topography near Corner)

T. 148 N. R. 30 W. 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 30 S. 5 Mer.

Section Corner common to Sections

4, 5, 6, and 9

Corner consists of a main pipe (not) in place

State condition fair

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 148
R 30
S-5

T 148
R-30
S-4

--

--

BT

BT

--

--

Species Stump Stump

Diameter 14" 14"

Bearing S 86 W N 21 E

Distance 43 ch 30 ch

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? _____

H. Anderson
(Signature)

10/26/34
(Date)

(Title) E-9

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 178 R. 30 Mer. *ST*