

B-9

Form 874-9—Revised May, 1918

U. S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 30 Mer.

24 Corner common to Sections

4, and 5

Corner consists of a stone (not) in place

State condition good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16 S</u>
---------------

<u>1/16</u>
-------------

--

--

<u>BT</u>
-----------

<u>BT</u>
-----------

--

--

Species Juniperus sp.

Diameter 10

Bearing N 15° E

Distance 19 30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

(Signature)

(Date) 11/13/30

(Title)

B-9

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

B-9 Mer.

R.

T.

U. S. Department of Agriculture  
FOREST SERVICE

..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 30 Mer.

CN 1/16

..... Corner common to Sections

4, 5, and .....

Corner consists of a Scrub post + concrete in place

State condition Fair

Dimensions above ground ..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ..... is located .....

..... Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Black Spruce - Dead

Diameter 8" DBH - 15' Tall

Bearing S-50° E

Distance 20'

Do you believe this to be a genuine Land Office Corner? .....

If not, why? No Reason


R. H. Johnston  
(Signature)

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree . . . . . inches diameter, on the side of . . . . . from which this Corner bears . . . . . chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *30* *5th* Mer.

*N 1/2* Corner common to Sections

....., *4*, and *5*

Corner consists of a *iron pipe* (not) in place



State condition *fair*

Dimensions above ground *12* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*4/6 S*

*1/6 S*

*BT*

*BT*

Species *SPROCE* *SPROCE*

Diameter *10"* *8"*

Bearing *N15E* *E*

Distance *.19ch* *.30ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? .....


*Murphy*  
(Signature)

*8/14/35*  
(Date)

(Title)

Metal Location Poster is on a *Stump* tree *6* inches diameter, on the *N E* side of *Stump* from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 R. 30 Mer. 5th

**U. S. Department of Agriculture**  
**FOREST SERVICE**

*Chippewa*..... NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. *148* R. *30* Mer. *5th*

*N 1/4* Corner common to Sections

....., *4*, and *5*

Corner consists of a *iron pipe* (not) in place

State condition *fair*

Dimensions above ground ..... *1 1/2* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

**CARDINAL POSITION**

**DIAGONAL POSITION**

--	--	--	--

N      W      S      E

--	--	--	--

NW   SW   SE   NE

Mound of ..... is located .....

..... Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> S	<i>1/4</i> S		
<i>B 1</i>	<i>B 1</i>		

Species *SPRUCE* *S. PRUCE*

Diameter *10"* *8"*

Bearing *N 15 E* *E*

Distance *120* *300*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? .....


*Massley*  
(Signature)

*8/14/35*  
(Date)

(Title)

Metal Location Poster is on a tree 6 inches diameter, on the *W. E.* side of *W. E.* from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 R. 32 S. 24 Mer.