

N-21

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th P. Mer.


Section Corner common to Sections
13, 14, 23, and 24

Corner consists of a In center of road (dot) in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Co. B. T. S. 23			
B. T.			

Species Aspen Fallen down

Diameter 9"

Bearing S. 24° 30' W.

Distance 83

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

K. V. Styler

(Signature)

Leader


5/3/38

(Date)

(Title)

N-21

(Make sketch of topography near corner)



Metal Location Poster is on a

Aspen

N. E.

tree 12 inches diameter, on the

side of Tree

N. 38° E.

0.95 chains distant.

Give any further facts which will aid in finding this

Corner again.

F. S. Section line marker post bears

South 21 lks. from corner.

T. 148 N. R. 30 W. 5th P. Mer.

N-21

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W 5th P. Mer.

Section Corner common to Sections
13, 14, 23, and 24

Corner consists of a Iron Pipe of 1.99 (not) in place
State condition

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Co. B.T.

<u>3</u> <u>23</u>			
-----------------------	--	--	--

<u>B.T.</u>			
-------------	--	--	--

Species Aspen Fallendown

Diameter 9"

Bearing S 24° 30' W.

Distance 83

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

K. V. Styler

(Signature)

Leader:

(Title)

5/3/38

(Date)

N-21

F.S. Section Line Marker Post
Bears South 21 Mts. from Corner

Corner again.

Give any further facts which will aid in finding this


0.95 chains distant.

from which this Corner bears N.38° E.

side of Tree

tree 12 inches diameter, on the N.E.

Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

T. 148N. R. 30W. 5th P. Mer.