

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *30W* *5<sup>th</sup>* Mer.  
*#14 - 1/16* Corner common to Sections

....., *1*, and *6*.....

Corner consists of a *pipe* (not) in place  
State condition *good*


Dimensions above ground *6"* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Survey*


*G. D. Bauch*  
(Signature)

*S.F.*  
(Title)

*11/21/35*  
(Date)

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

T. 148N R. 30W 5th Mer. H-21