

## U. S. Department of Agriculture

## FOREST SERVICE

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. S. 5 P. Mer.

Quarter Corner common to Sections

, 11, and 12

Corner consists of a Ir. Pip 1" x 6" (not) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Co. BT.			
BT.			

Species *Aspen sp.*

Diameter 5"

Bearing N. 35° W.

Distance 5'

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

K. V. Styler

(Signature)

Leader


(Title)

7/6/38

(Date)

(Make sketch of topography near Corner)

T. 148N. R. 30W. 5th P. Mer. 6-21



Metal Location Poster is on a *Aspen*

tree *7* inches diameter, on the *West*

side of *Tree*

from which this Corner bears *S 85° W*

*0.21* chains distant.

Give any further facts which will aid in finding this

Corner again.