

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th Mer.

1/4 corner Corner common to Sections

....., 1, and 6

Corner consists of a Pipe & post (not) in place

State condition Good

Dimensions above ground 32 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT			

Species

Diameter

Bearing E.

Distance 59.5 Links

Do you believe this to be a genuine Land Office Corner?

If not, why?

G. D. Bauch

G. D. Bauch

(Signature)

Junior Forester


(Title)

11/27/35

(Date)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148 N. R. 30 W. 5th Mer.