

U. S. Department of Agriculture

FOREST SERVICE

A-2-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 30W. 513P. Mer.

Meander Corner common to Sections 6, and 31 - T. 149N. R. 30W.

Corner consists of a Cedar Post (not) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT BT Orig. notes

Species Tam. Stp. Tam. Stp. fern fern
Diameter 10" 7 7 7
Bearing N. 45° W S. 71° W N 42° W N 83° W
Distance 34 26 34 26

Do you believe this to be a genuine Land Office Corner? YES

If not, why? \_\_\_\_\_

John A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

7/10/39

(Date)

A-2-3

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this


0.32 chains distant.

from which this Corner bears N. 79° E

side of Tree

tree 5 inches diameter, on the East

Metal Location Poster is on an Elm



(Make sketch of topography near Corner)

T. 198 N. R. 30 W.

S. 49 P.

A-2-3 Mer.

A-2-3

Form 874-9—Revised May, 1918

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th. P. Mer.

Meander Corner common to Sections

6, and 31 T. 149 R30W

Corner consists of a Cedar Post (~~rod~~) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BTs

--	--	--	--

BT	BT		
----	----	--	--

Species Tam. Stp. T. Stp.

Diameter 10" 7"

Bearing 74°45' W 76° S 71' W

Distance 34 26

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

John A. Gjelhaug

(Signature)

Jr. Civil Engl

(Title)

7/10/39

(Date)

A-2

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this


0.32 chains distant.

from which this Corner bears N79°E

side of Tree

tree 5 inches diameter, on the East

Metal Location Poster is on a Elm



(Make sketch of topography near Corner)