

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 30W. 53P. Mer.

Meander. Corner common to Sections
12, and 7 T. 148N.
R. 29W.

Corner consists of a Tamle Post (not) in place



State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Down Tamle Down Birch

Diameter 4" 12"

Bearing N. 10° E. N. 40° W.

Distance 29 29

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

H. Hoard

(Signature)

Compass Man

(Title)

2/12/40

(Date)

$$\begin{array}{r} 144 \\ 4 \overline{) 576} \\ \underline{160} \\ 176 \\ \underline{176} \\ 0 \end{array}$$

$$\begin{array}{r} 144 \\ 4 \overline{) 576} \\ \underline{160} \\ 176 \\ \underline{176} \\ 0 \end{array}$$

Corner again.

Give any further facts which will aid in finding this


0.09% chains distant.

from which this Corner bears N.90°E.

side of Tree

tree 10 inches diameter, on the N.E.

Metal Location Poster is on a Tangle.



(Make sketch of topography near Corner)

T. 198N. R. 30W. S. 74 P. 25 Mer.

Form 874-9--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 30 W 5th P. Mer.

Meander Corner common to Sections
12, and 7 T148N R 29 W

Corner consists of a Tam'c. Post (~~not~~) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig.	B.T.'s		
B.T.	B.T.		

Species Down Tam'c. Down Birch

Diameter 4" 12"

Bearing N 10°E N 40°W

Distance 24 29

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Hugh M. Hoard

(Signature)

Compass Man


(Title)

2/12/40

(Date)

Metal Location Poster is on a Tamarack tree 10 inches diameter, on the N.E. side of Tree from which this Corner bears $0.09\frac{1}{2}$ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N. R. 30 W. 5th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 30 W 5th P. Mer.

Hearder Corner common to Sections

12, and 7 T148N R 29 W

Corner consists of a Tan's Post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.'s		
B.T.	B.T.	

Species Down Tan's, Down Birch

Diameter 4" 12"

Bearing N 10° E N 40° W N 12 W

Distance 24 29 19

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Hugh M. Hoard
(Signature)

2/12/40
(Date)

Comptroller
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.095

from which this Corner bears N 40° E

side of Tree

tree 10 inches diameter, on the N.R.

Metal Location Poster is on a **TRAIL**



Make sketch of topography near Corner

T. 148 N R. 30 W 5th P. Mer.