

U. S. Department of Agriculture

Submitted to FOREST SERVICE

J-1
J-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31432 5th Mer.

Section Corner common to Sections 18, 12, and 13

Corner consists of a Stake in place

State condition Poor (Est. New)

Dimensions above ground 4x4x30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T148ND R31W S. 7

T148 R32 S13

T148R31 S18

--

BT

BT

BT

--

Species Tamar. Spruce Spruce

Diameter 8" 6" 3"

Bearing N20°30'E S73°6' S40°E

Distance 23chs. 23chs. 19chs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

B. Brooks


(Signature)

3-28-36

(Date)

(Title)

Corner again.
 Give any further facts which will aid in finding this
 chains distant
 from which this Corner bears **N20°30'E**
 side of
 tree **1/4** inches diameter, on the **SW**
 Metal Location Poster is on a **Tom or Rock**



(Make sketch of topography near Corner)

T. L. W. B. R. 11433 S. R. 314
 1-1-1

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE



*J-1
 already
 posted
 J-1*

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 & 32 5th Mer.
 Section Corner common to Sections
 18, ~~7~~, 12, and 13

Corner consists of a Stake (not) in place
 State condition Poor (Est. New)

Dimensions above ground 4 x 4 x 30 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 148 N. R. 31 W. S. 7	T. 148 R. 32 S. 13	T. 148 R. 31 S. 18	
BT	BT	BT	

Species Tan. Spruce spruce
 Diameter 8" 6" 3"
 Bearing N. 20° 30' E. S. 73° W. S. 40° E.
 Distance 23 ch. 23 ch. 13 ch.

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

B. Brooks

B. Brooks
 (Signature)

3/28/36
 (Date)

Enrollee
 (Title)

Corner again.

Give any further facts which will aid in finding this


• 23 ch. chains distant.

from which this Corner bears N. 20° 30' E.

side of Tree

tree 14 inches diameter, on the SW

Metal Location Poster is on a Tamarack



(Make sketch of topography near Corner)

T. 148 N. R. 31 W. 5th J-Mer