

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

*238*  
*36*  
*V-8*

*Chippewa* NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. *148* R. *31* Mer. *546*

*E 1/4* Corner common to Sections  
 \_\_\_\_\_, *32*, and *29*

Corner consists of a *iron pipe* (not) in place  
 State condition *good*

Dimensions above ground \_\_\_\_\_ *3* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/65</i>	<i>1/45</i>		
<i>BT</i>	<i>BT</i>		

Species *Balsam Birch*

Diameter *10"* *6"*

Bearing *N 89 W* *S 50 W*

Distance *19 ch* *14 ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Murphy*  
 (Signature)

*9/28/35*  
 (Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

07 chains distant.

from which this Corner bears


S. 71° 0' E

side of

tree 16 inches diameter, on the

Metal Location Poster is on a

Corner



(Make sketch of topography near Corner)

T. 1118 R. 31 V. 8 S. 21 N. Mer. K-9

U. S. Department of Agriculture

FOREST SERVICE

P 15-8  
36  
V-8

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 128 R. 31 5th Mer.

E 1/4 Corner common to Sections

32, and 29

Corner consists of a *iron pipe* (not) in place


State condition *Good*

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Balsam Birch*

Diameter *10"* *6"*

Bearing *N39W* *S50W*

Distance *190* *146*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*[Signature]*  
(Signature)

*9/25/35*  
(Date)

(Title)

Give any further facts which will aid in finding this Corner again.

0.7 chains distant.

from which this Corner bears S 40 E side of *Corner*

Metal Location Poster is on a tree 14 inches diameter, on the *side*

	Sec.	32	Sec.
	Sec.		
	Sec.	29	Sec.
	Sec.		

(Make sketch of topography near Corner)

T. 148 R. 31 S. 40 E. V. 18 V. 18 V. 18

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

V-8  
V-8

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31 S Mer.


Corner common to Sections  
32, 29, and

Corner consists of a Iron Pipe in place  
State condition good


Dimensions above ground 1 1/2 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam 9" 310° 13 FT  
Diameter Buck 7" 210° 8 FT  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? No county survey

P. H. ...  
(Signature)


(Date)

D. P. ...  
(Title)

.....  
.....  
.....  
.....  
.....

*Corner again.*  
*Tag also on 16.085*

Give any further facts which will aid in finding this  
..... chains distant.  
from which this Corner bears  
..... side of  
tree *5* inches diameter, on the  
Metal Location Poster is on a *Post*



(Make sketch of topography near Corner)