

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-19
R-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31 5th Mer.

1/4 Corner common to Sections
23, 26, _____, and _____



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____


If not, why? _____

Duff M Johnson
(Signature)
fall-1957
(Date) _____ (Title)

Corner again.
Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
side of

tree, ^{tree} 5 inches diameter, on the ^{South} side.
Metal Location Poster is on a ^{black spruce}



(Make sketch of topography near Corner)

R-19
Mer.
R-19

578

R. 31

T. 148