

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-20

E-20

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31W 5th P. Mer.

East Sixteenth..... Corner common to Sections

.....,, 2, and 11.....

Corner consists of a Scribed Post (one) in place

State condition Good.....

Dimensions above ground 30..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Subdivision Survey.....

H. M. Hoard

(Signature)

Compass Man

(Title)

3/8/40

(Date)

Corner again.

Give any further facts which will aid in finding this


0.25 chains distant.

from which this Corner bears N. 86° E.

side of Tree

tree 4 inches diameter, on the East

Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

T. 148 N. R. 31W. Sth P. Mer. E-20

U. S. Department of Agriculture

FOREST SERVICE

E-20

E-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31W. 54P. Mer.

East Sixteenth Corner common to Sections

-----, -----, 2, and 11

Corner consists of a scribed post (not) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Subdivision

Survey

H. M. Hoard

(Signature)


Compass Man

(Title)

3/8/40

(Date)

Metal Location Poster is on a *Aspen* tree *4* inches diameter, on the *East* side of *Tree* from which this Corner bears *0.25* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N. R. 31 W. S. 1/4 P. 6-20
 Mot. E-20

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-20
E-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31W 5th P. Mer.

East Sixteenth Corner common to Sections
_____, _____, 2, and 11

Corner consists of a Scribed Post (____) in place

State condition Good

Dimensions above ground 50 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No


If not, why? County Subdivision Survey

H. M. Hoard
(Signature)

3/8/40
(Date)

Compass Man
(Title)

Metal Location Poster is on a **12** **Aspen** tree \odot inches diameter, on the **East** side of **Tree** from which this Corner bears **N. 86° E.** **0.25** chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)