

R-21

U. S. Department of Agriculture

Submitted 66 FOREST SERVICE

R-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 31 W 5th Mer.

Sec. 1 Corner common to Sections 23, 24, 25, and 26

Corner consists of a Post ~~stone~~ in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

A. D. Bauch

(Signature)


12/13/35
(Date)

J. F.
(Title)

[Faint, illegible text on ruled lines]

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148N R. 31W 5th Mer. R-21

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-21
already
Posted
R-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.
Section

Corner common to Sections

23, 24, 25, and 26

Corner consists of a Post (not) in place

State condition

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species TAM Cedar

Diameter 10" 8"

Bearing NW SW

Distance 15L 20L

Do you believe this to be a genuine Land Office Corner?

If not, why?

G. J. Bauch

G. J. Bauch
(Signature)

Junior Forester

12/13/35


(Date)

(Title)

.....
.....
.....
.....
.....
.....

*Corner in center
of all four*

Corner is in
Give any other facts which will aid in finding this
.....
.....
from which this Corner bears
.....
side of
.....
tree inches diameter, on the
.....
Metal Location Poster is on a



(Make sketch of topography near Corner)

R-21
R-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T 148 N. R. 31 W. S. Mer.

Section Corner common to Sections

23, 24, 25, and 26

Corner consists of a Cedar Post in place


State condition: Squashed Cedar Post (Established today)

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Tamarack Cedar Jam Cedar*

Diameter *10" 8" 80 6*

Bearing *NW SW S 22 E N 28 E*

Distance *152 202 21 18*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

11/6/57
(Date)

J. S. Stephenson
(Signature)
Dist. Ranger
(Title)

Corner again.
 Post is in center of old logging
 road. Cedar B.T. Sec. 26 is
 still standing but dead. might last
 20-30 years.
 Tamarack B.T. Sec. 24 is
 fallen & well decayed. B.T.
 scribbles is still visible.
 Blazed Sec. Line west from
 corner on Var. 12°

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of Post,

tree inches diameter, on the West

Metal Location Poster is on a 6" Cedar Post



(Make sketch of topography near Corner)

T. H. B. N. R. 31 W. Mer. R-31

U. S. Department of Agriculture

FOREST SERVICE

R-21

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 31W 5 Mer.

Sec.

Corner common to Sections

24, 25, 23, and 26

Corner consists of a Post (not) in place



State condition poor

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species T C

Diameter 10" 8"

Bearing NW SW

Distance 156. 204.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

G. D. Bauch

(Signature)

S.F.


(Title)

3/12/35

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

The correction is in the center of an old tote road



(Make sketch of topography near Corner)

T. 149N R. 31W R. 15
R-51 Met.

U. S. Department of Agriculture

FOREST SERVICE

*discovery
Pit
R-21*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Section Corner common to Sections
24, 25, 23, and 36

Corner consists of a Post (not) in place

State condition Poor

Dimensions above ground 18 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam. Cedar

Diameter 10" 8"

Bearing NW SW

Distance 15 lks. 20 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. D. Bauch

G. D. Bauch

(Signature)

Junior Forester

12/31/35

(Date)

(Title)

road.

The corner is in the center of an old

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

R-21
Mer. 1
P-d

5th

31 W.

R. 148 N.

T. 148 N.