

U. S. Department of Agriculture
FOREST SERVICE

D-21

D-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31W. 54P. Mer.

South Sixteenth Corner common to Sections
_____, _____, 1, and 2

Corner consists of a 1" Iron Pipe (not) in place

State condition Good

Dimensions above ground _____ 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.

<u>BT</u>	<u>BT</u>		

Species W. Pine Sp. W. Pine Sp.

Diameter 24" 18"

Bearing N29°E. S97°E.

Distance 40 1/2 50

Do you believe this to be a genuine Land Office Corner? No

If not, why? County subdivision
Survey.

H. M. Hoard

(Signature)

Compass Man.

(Title)

3/8/40
(Date)

Corner again.

Give any further facts which will aid in finding this

0.35 1/2 chains distant.


from which this Corner bears

N. 8. W.

side of *Stump*

tree 8 inches diameter, on the *North*

Metal Location Poster is on a *W. Pine Stump*



(Make sketch of topography near Corner)

T. 148N. R. 31W.

574P. 0-21

Mo. 0-21

0-21

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

D-21
D. 21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th P. Mer.


South Sixteenth Corner common to Sections
.....,, 1, and 2

Corner consists of a 1" Iron Pipe (not) in place
State condition Good

Dimensions above ground 6 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine Stps W. Pine Stps

Diameter 24" 18"

Bearing N. 24° E. S. 47° E.

Distance 40 1/2 50

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Subdivision Survey

H. V. Hoard
(Signature)

Compass Man
(Title)

3/8/40
(Date)

U. S. GOVERNMENT PRINTING OFFICE: 1909 8-7394

Corner again.

Give any further facts which will aid in finding this


0.558 chains distant.

from which this Corner bears N. 8° W.

side of Stamp

tree 8 inches diameter, on the North

Metal Location Poster is on a W. pins Stamp



(Make sketch of topography near Corner)

Form 874-9--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

D-21

D-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th P. Mer.


South Sixteenth Corner common to Sections
_____, _____, 1, and 2

Corner consists of a 1" Iron Pipe (~~not~~) in place
State condition Good


Dimensions above ground 6 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County	B.T.'s		
BT	BT		

Species W. Pine Stp. W. Pine Stp.

Diameter 24" 18"

Bearing N. 24° E. S. 47° E.

Distance 40 $\frac{1}{2}$ 50

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County Subdivision Survey


H. M. Hoard
(Signature)

Compass Man
(Title)

3/8/40
(Date)

Corner again.

Give any further facts which will aid in finding this
0.557 chains distant.
from which this Corner bears N. 8° W.
side of Stump
tree 8 inches diameter, on the North
Metal Location Poster is on a W. pine Stump.



(Make sketch of topography near Corner)