

U. S. Department of Agriculture

FOREST SERVICE

J-22
J-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *31W* *5* Mer.

#2-1/6

Corner common to Sections

....., and *13*

Corner consists of a *Stake and pipe* (not) in place



State condition *good*

Dimensions above ground *28* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance


Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Survey*

G. D. Bouch
(Signature)

S. F.
(Title)

12/19/35
(Date)



(Make sketch of topography near Corner)

T. W. N. R. 3/11
 5-11.5.22
 Met. 1-22

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.