

U. S. Department of Agriculture

Submitted CG FOREST SERVICE

L-23
L-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 31W 5th Mer.

Cor 1/4

Corner common to Sections

and 13

Corner consists of a post in place

State condition good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species T T

Diameter 4" 4"

Bearing NW SW

Distance 15L 8L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. D. Bauch


(Signature)

12/17/35
(Date)

J. F.
(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148N R. 31W
 Sec 4-23
 Mc
 1-23