

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 140N. R. 31W. 512P. Mer.

Quarter Corner common to Sections

1, and 12

Corner consists of a 1" Iron Pipe (not) in place


State condition Good

Dimensions above ground 6 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.



B.T.

Species Pine sp

Diameter 12"

Bearing S. 24° W.

Distance 21

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. M. Hoard

(Signature)

Compass Man

(Title)

3/7/190

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.50


From which this Corner bears

8.21° E.

side of *Tree*

tree 6 inches diameter, on the *S.E.*

Metal Location Poster is on a *N. Aspen*



(Make sketch of topography near corner)

T. 148N. R. 31W.

514 P. E-23 Mer.

E-23

E-23
E-23

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31 W. 5th P. Mer.
Quarter Corner common to Sections

1, and 12

Corner consists of a 1" Iron Pipe (~~not~~) in place
State condition Good

Dimensions above ground 6 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.			
B.T.			

Species Pine Stp.

Diameter 12"

Bearing S. 24° W.

Distance 21

Do you believe this to be a genuine Land Office Corner? Yes


If not, why?

H. M. Hoard
(Signature)

Compass Man
(Title)

3/7/40
(Date)

Metal Location Poster is on an **11** inches diameter, on the **S.E.** side of **Tree** from which this Corner bears **0.50** chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

E-23
Mer.

T. 148 N. R. 31 N.

U. S. Department of Agriculture
FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31 W. 5th P. Mer.
Quarter Corner common to Sections

1, and 12

Corner consists of a 1" Iron Pipe (~~set~~) in place
State condition Good

Dimensions above ground 6 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.			
B.T.			

Species Pine Stp.

Diameter 12"

Bearing S.24°W.

Distance 21

Do you believe this to be a genuine Land Office Corner Yes

If not, why? _____

H. M. Hoard

(Signature)

Compass Man

(Title)

3/7/40

(Date)

