

U. S. Department of Agriculture
FOREST SERVICE

D-23

D-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 31W. 519P. Mer.

South C-C 1/16 Corner common to Sections

_____, _____, _____, and 1

Corner consists of a 21 Iron Pipe 1" (~~rod~~) in place

State condition Good

Dimensions above ground _____ 6 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Pine sp. Pine sp.

Diameter 14" 24"

Bearing N.59°W. S.98°W.

Distance 35 59

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Subdivision

Survey

H. M. Hoard

(Signature)

Compass Man

(Title)

3/14/40

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. 007

From which this Corner bears N. 84° E.

side of Tree

tree 4 inches diameter, on the East

Metal Location Poster is on a 77 Aspen



(Make sketch of topography near Corner)

D-23

T 148 N. R. 31 W. 5-73 P. D-23

U. S. Department of Agriculture

FOREST SERVICE

D-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th. P. Mer.
 South C-C 1/8 Corner common to Sections

-----, -----, -----, and 1



Corner consists of an Iron Pipe 1" (not) in place
 State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.Ts.			
BT	BT		

Species Pine Stp. Pine Stp.

Diameter 14" 24"

Bearing N. 54° W. S. 48° W.

Distance 35 59

Do you believe this to be a genuine Land Office Corner? No


If not, why? County Subdivision Survey

H. W. Hoard
 (Signature)

5/14/40
 (Date)

Compass Man
 (Title)

Metal Location Poster is on an Aspen tree 4 inches diameter, on the East side of tree from which this Corner bears N. 84° E. 0.07 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N. R. 31 W. 5th P. 0-23 Mer.

0-23

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

D-23
D-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th. P. Mer.
South C-C 16 Corner common to Sections
-----, -----, -----, and 1

Corner consists of an Iron Pipe 1" (nom) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.Ts.			
BT	BT		

Species Pine Stp. Pine Stp.

Diameter 14" 24"

Bearing N. 54° W. S. 48° W.

Distance 35 59

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Subdivision Survey

Hoard

(Signature)

3/14/40
(Date)

Compass Man
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of


tree 4 inches diameter, on the

Metal Location Poster is on

N. 81. E.

East

100



(Make sketch of topography near Corner)