

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-24
L-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *31W* *5th* Mer.

Corner common to Sections _____, _____, and *13*

Corner consists of a *pipe* ~~(not)~~ in place
State condition *good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>BT</i>		

Species *A* *Stamp*

Diameter *14"*

Bearing *SE* *ESE*

Distance *50L* *10L*

Do you believe this to be a genuine Land Office Corner? *yes*
If not, why? _____

12/18/35
(Date)

J. D. Bauch
(Signature) *S.F.*
(Title)

L-24

U. S. Department of Agriculture

Submitted G.G. FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 31 W 5th Mer.

Mc on 1/4 line Corner common to Sections W of E 1/4 cor, and 13

Corner consists of a Post in place

State condition good

Dimensions above ground 34 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	Mc		
--	----	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

O			

Species Cedar

Diameter 8"

Bearing NW

Distance 10 L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. D. Bauch

(Signature)

12/19/35


(Date)

J. J.

(Title)

Corner again.
The corner is directly
W. of the fence corner as
shown above

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant,
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 148 N. R. 31 W. 524 6-24

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-24
L-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 31 W 5 Mer.

#8 1/16 Corner common to Sections
_____, _____, and 13

Corner consists of a pipe (not) in place
State condition good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? County survey

CORNER

G. D. Rauch

(Signature)


12/10/35

(Date)

(Title) J. J.

Corner again.
There is a large open
(4" DBH) S. S. E. 30 W.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 148 N R. 31 W
5th
Mar 24
6-24

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-24
24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *31W* *5th* Mer.

#8 1/16 Corner common to Sections
....., and *13*


Corner consists of a *pipe* (~~not~~) in place
State condition *good*

Dimensions above ground *4"* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *No.*

If not, why? *County survey corner.*

J. D. Bouch
(Signature)

S.F.
(Title)

10/17/35
(Date)

*There is a large aspen
(W. DBH) 5.5 x 307*

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.	<i>M6 M6 { Lake</i>	Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

*7-24
M6*

R. 31M

T. 148N

U. S. Department of Agriculture
FOREST SERVICE

L-24
already
Posted
E-24

Chipmewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

West 1/4 Corner common to Sections

13, and

Corner consists of a Post (not) in place



State condition Good.

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar

Diameter 8"

Bearing NW

Distance 10 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. D. Bauch

(Signature)

Junior Forester

(Title)


12/19/35

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

The corner is directly west of the fence corner as shown above.



(Make sketch of topography near corner)

T. 148 N. R. 31 W. 5th L-34 Mer

1-24

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-24
L-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

#8 - 1/16 Corner common to Sections
13, and

Corner consists of a pipe (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	BT		

Species Aspen stumps

Diameter 14"

Bearing SE E x SE

Distance 50 links 10 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. Bauch

G. Bauch

(Signature)

~~Enrollee~~

J. F.

(Title)

12/18/35

(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

6-24
M.G.

5th

R. 31 W.

T. 148 N.

1