

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P 69  
35

CHIPPEWA NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 R. 25 5TH Mer.



1/4 Corner common to Sections  
8, and 9

Corner consists of a TAM. STAKE (not) in place  
State condition FAIR

Dimensions above ground 4x4" x 36" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species TAM. TAM (STUB)

Diameter 3" 3 1/2"

Bearing N 17 1/2° E N 89° W

Distance 10 IK. 18 IK.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Dec 12, 1935  
(Date)

H. C. Norman  
(Signature)  
J. Forester  
(Title)

Corner again.

Give any further facts which will aid in finding this


0.15 chains distant.

from which this Corner bears N 40°

side of TREE

tree 4 inches diameter, on the NW

Metal Location Poster is on a SPRUCE



(Make sketch of topography near Corner)

T 149 R 25 5TH. Mer. 6-9