

U. S. Department of Agriculture

FOREST SERVICE

23

P

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5th Mer.

Quarter Corner common to Sections

.....,, 19, and 30

Corner consists of a Oak Post (~~not~~) in place

State condition Good (Set New Post)

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W. Pine str.

Diameter 1.8"

Bearing N. 40° E.

Lks. Distance 7

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

.....

J. A. Gjelhaug

(Signature)

Jr. Civil Engr.

(Title)

1/3/36
(Date)

Corner again.

Give any further facts which will aid in finding this


0.01 chains distant.

from which this Corner bears *NW 1/4*

side of *Tree*

tree *B* inches diameter, on the *SE*

Metal Location Poster is on a *Beam of GI*



(Make sketch of topography near Corner)

T. 149N R. 26W 5th Mer.