

U. S. Department of Agriculture

FOREST SERVICE

E-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 26 5th Mer.

Section Corner common to Sections
6, 5, 7, and 8

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 6			
B.T			

Species Spruce stump

Diameter 8"

Bearing N 60° W

Distance 50 Links

Do you believe this to be a genuine Land Office Corner? No

If not, why? Scribed with

Jack Knife

County Resurvey

J. B. Ames

(Signature)

Engineer

(Title)

1-22-34

(Date)

E-5

Corner is in Middle of Road.

Corner again.

Give any further facts which will aid in finding this


50 LINKS ~~about~~ distant.

From which this Corner bears N 60° W

side of Road.

tree 8 inches diameter, on the West

Metal Location Poster is on a Spruce B.T.



(Make sketch of topography near Corner)

T. 149 R. 26 S. Mer.